



ATTENTION – THIS SIGN SHALL NOT BE REMOVED.

CAUTION: THIS IS AN UNVENTED ATTIC BY DESIGN.

- No modification may be made to this unvented condition.
- The attic shall not be vented.
- Holes into the unvented attic shall be immediately repaired and sealed.
- Penetrations of the ceiling or wall membrane between the unvented attic and living space, other than the horizontal access hatch, must be protected in an approved manner.
- This unvented attic shall not be used for storage.

SEE INTERTEK CODE COMPLIANCE RESEARCH REPORT CCRR-1121, 0298, OR 0293 FOR MORE DETAILS.

ADDITIONAL LIMITATIONS OF USE PER CCRR-1121, 0298, OR 0293:

- Entry to the attic is only to service utilities and no storage is permitted.
- There are no interconnected attic areas.
- Air in the attic is not circulated to other parts of the building.
- Combustion air is provided in accordance with IMC (International Mechanical Code) Section 701 [Sections 701 and 703].

If any of these limitations are not met, follow ICC R316 code requirements for thermal or ignition barrier fire protection. Contact the CSFI Technical Service Team at 844.922.2355

